




Step 1



Step 2



Step 3



K T-Bar (1pc)	Q Cap nut (1pc)
L Large Blade (1pc)	A Bottom Bar (1pc)
M Washer concave surface (1pc)	B Two-Prong Stake (1pc)
N Tube (1pc)	C Middle Bar (1pc)
O Small blade (1pc)	E Top Bar (1pc)
P Elastic ring (1pc)	